



— IWATA REVOLUTION M SERIES AIRBRUSHES —
MASTER PARTS LIST

#	ITEM DESCRIPTION	PRICE CODE	ITEM #	HP-M1	HP-M2	#	ITEM DESCRIPTION	PRICE CODE	ITEM #	HP-M1	HP-M2
1	Needle Cap HP-M1 .3 mm	A	I 701 4	■	x	17	Main Lever	C	I 714 3	■	■
	Needle Cap HP-M2 .4 mm	A	I 701 5	x	■	23	Needle HP-M1 .3 mm	E	I 717 6	■	x
2	Nozzle Cap HP-M1 .3 mm	C	I 702 4	■	x		Needle HP-M2 .4 mm	E	I 717 7	x	■
	Nozzle Cap HP-M2 .4 mm	C	I 702 5	x	■	24	Needle Chucking Nut	A	I 715 3	■	■
4	Nozzle HP-M1 .3 mm	E	I 704 4	■	x	28	Lid HP-M1	C	I 718 3	■	x
	Nozzle HP-M2 .4 mm	E	I 704 5	■	x		Lid HP-M2	C	I 718 4	■	x
9	Needle Packing Screw	B	I 725 4	■	■	33	Fluid Adjustment Valve	F	I 722 2	■	■
10	Piston O-Ring	A	I 145 1	■	■	32	Spanner	A	I 765 1	■	■
12	Air Valve Set	F	I 712 2	■	■						

■ = yes x = no opt = optional